

कार्यालय कार्यपालन यंत्री लोक निर्माण विभाग(भ/स) संभाग पन्ना (म0प्र0)

E-Mail ID-cepwdpan@gmail.com

Phone/Fax No. 07732-252006

कर्मक/ 175 /तक./भवन/2022-23

पन्ना दिनांक 13.01.2023

प्रति,

✓
प्राचार्य
लिस्सू आनन्द विद्यालय,पन्ना
जिला, पन्ना म0प्र0

विषय:- विद्यालय भवन, सेफ्टी सर्टीफिकेट प्रदाय करने बावत्।


संदर्भ:- आपका आवेदन दिनांक 10.01.2023।

--- 0 ---

उपरोक्त विषयान्तर्गत संदर्भित आवेदन के संबंध में लेख है कि लिस्सू आनन्द विद्यालय पन्ना जिला पन्ना का अनुविभागीय अधिकारी लोक निर्माण विभाग उपसंभाग पन्ना प्रथम द्वारा दिनांक 12.01.2023 को निरीक्षण कर प्रतिवेदन प्रस्तुत किया गया है। प्रतिवेदन में लेख किया गया है कि भवन पूर्ण रूप से आर.सी.सी. से निर्मित है सुदृढ एवं मजबूत है।

अतः अनुविभागीय अधिकारी लोक निर्माण विभाग उपसंभाग पन्ना प्रथम द्वारा प्रस्तुत प्रतिवेदन के आधार पर संबंधित भवन शैक्षणिक गतिविधियों के संचालन हेतु पूर्ण रूप से सुरक्षित है।

सहपत्र :- निरीक्षण प्रतिवेदन ।


(ए.बी. साहू)
कार्यपालन यंत्री
लो. नि. वि. (भ/स) संभाग पन्ना (म0प्र0)

OFFICE OF THE EXECUTIVE ENGINEER

P.W.D. DIVISION OFFICE, PANNA DISTT. PANNA (M.P.)

INSPECTION REPORT (To be filled by the inspecting Officer)

Name of the Officer :

Name of the School : LISIEUX ANAND SCHOOL, PANNA(M.P.)

Location with name of Education distt : Tahasil- Panna , Distt. Panna (M.P.)

Classification of Building : 1698 Sq.mtrs (Ground floor)
: 1698 Sq.mtrs (1st floor)
: 1698 Sq.mtrs (2nd floor)

Total Built up Area : 5094 Sq.mtrs

Period for which the certificate is issued : 2023-24

Nature of defect if any :-

- (a) Foundation and basement : Not Applicable
(b) Superstructure : Not Applicable
(c) Doors and windows : Not Applicable
(d) Wood works wrought and put up : Not Applicable
(e) Roof : Not Applicable
(f) Flooring : Not Applicable
(g) Miscellaneous (cracks etc) : Not Applicable

Any major defects noticed which will render the building unsafe in any manner : No


Whether maintenance works have been done properly : Yes


Whether the structure is sound or not for conduction classes : **Building is sound and safe**

- Note :** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind exposure of flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

School building of LISIEUX ANAND SCHOOL, PANNA was inspected by me on and found to be fit to conduct classes for the period of 2023-24 for the reasons stated above.

Place : Panna (M.P.)
Date : 13/01/2023
No. :


Sub-Divisional Officer
P.W.D. (B/R) Sub-Dn. Panna 1st

c/s

Executive Engineer
P.W.D. (B/R) Div.-Panna

